Release Notes

Seagate® Nytro™ WarpDrive® and Nytro XP6209 Application Acceleration Card r112.00.06.00

XP6209-4B2048

DB07-000147-00
September 2014

Document Revision History

Revision	Date	Description of Change
NA	September 2014	Initial product version.

© 2014, Seagate Technology LLC. All rights reserved. Printed in USA. Seagate, Seagate Technology and the Wave logo are registered trademarks of Seagate Technology LLC in the United States and/or other countries. Nytro, Nytro WarpDrive, RAISE, DuraClass, DuraWrite, RAID, SandForce, SandForce Driven and the SandForce Driven logo are either trademarks or registered trademarks of Seagate Technology LLC or one of its affiliated companies in the United States and/or other countries. All other trademarks or registered trademarks are the property of their respective owners.

No part of this publication may be reproduced in any form without written permission of Seagate Technology LLC.

Call 877-PUB-TEK1 (877-782-8351) to request permission.

When referring to drive capacity, one gigabyte, or GB, equals one billion bytes and one terabyte, or TB, equals one trillion bytes. Your computer's operating system may use a different standard of measurement and report a lower capacity. In addition, some of the listed capacity is used for formatting and other functions, and thus will not be available for data storage. Actual data rates may vary depending on operating environment and other factors. Nytro products are not intended for use in life-support appliances, devices, or systems. Use of any Nytro product in such applications without written consent of the appropriate Seagate officer is prohibited. Seagate reserves the right to change, without notice, product offerings or specifications. Seagate reserves the right to change, without notice, product offerings or specifications.

Seagate Technology Support Services

For information regarding online support and services, visit: http://www.seagate.com/about/contact-us/technical-support/

Available services include:

- Presales & Technical support
- Global Support Services telephone numbers & business hours
- Authorized Service Centers

For information regarding Warranty Support, visit: http://www.seagate.com/support/warranty-and-replacements/

For information regarding data recovery services,
visit: http://www.seagate.com/services-software/data-recovery-services/

For Seagate OEM and Distribution partner portal, visit: http://www.seagate.com/partners/

For Seagate reseller portal, visit: http://www.seagate.com/partners/my-spp-dashboard/

Seagate® Nytro™ WarpDrive® and Nytro XP6209 Application Acceleration Card Release Notes

These release notes correspond to the current release of the firmware, drivers, and utilities for the Seagate® Nytro™ WarpDrive® and Nytro XP6209 Application Acceleration cards release r112.00.06.00.

For more information about the complete list of features supported, refer to the *Seagate® Nytro™ XP6000 Series Application Acceleration Cards Product Brief* and *Seagate® Nytro™ XP6000 Application Acceleration Card User Guide*.

1.0 SUPPORTED PRODUCTS

The following products use the Seagate Nytro WarpDrive and Nytro XP6209 firmware.

Table 1 Nytro WarpDrive and Nytro XP6209 Products

DEVICE NAMES	MODEL NAMES	USABLE CAPACITY
Seagate Nytro XP6209	XP6209-4B2048	1796 GB

2.0 SOFTWARE COMPONENTS AND DRIVERS

The following table lists the current versions of the software components for the Nytro WarpDrive and Nytro XP6209 cards.

Table 2 Nytro WarpDrive and Nytro XP6209Cards Software Components

SEAGATE DRIVER	VERSION
Microsoft® Windows® ■ Windows Server® 2012 R2 x64 ■ Windows Server 2008 R2 SP1 x64 ■ Windows Server 2008 R2 SP2 x64 and x32 ■ Windows 8 R2 x64 and 32 ■ Windows 7 SP1 x64 and x32 ■ Windows Server 2003 R2 SP2 x64 and x32 ■ Windows Vista® SP2 x64 and x32	Version 2.10.68.00
■ Solaris® 10x86 ■ Solaris 10 and 11	Operating system built-in driver
SUSE® Linux® Enterprise Server (SLES™) x64 and x32 ■ 10 SP0 to SP4 ■ 11 SP0 to SP3	Version 18.00.01.00-1
CentOS® x64 and x32 ■ 5.3 to 5.10 ■ 6.0 to 6.5 (RPM binary is available only from CentOS 6.3, for other versions, use Red Hat® Enterprise Linux (RHEL) RPMs)	Version 18.00.01.00-1
Ubuntu® x64 and x32 ■ 10.04, 11.1, and 12.04	Version 18.00.01.00-1
Debian® x64 and x32 ■ 6.0.5 and 6.0.7 **NOTE** Use the same driver.	Version 18.00.01.00-1
Fedora® x64 and x32 ■ 17 and 18	Version 18.00.01.00-1

Table 2 Nytro WarpDrive and Nytro XP6209Cards Software Components (continued)

RHEL x64 and x32 ■ 5.0 to 5.10 ■ 6.0 to 6.5	Version 18.00.01.00-1
Oracle® Enterprise Linux (OEL™) x64 and x32 ■ 5.4 to 5.9 ■ 6.0 to 6.4	Version 18.00.01.00-1
VMware® x64 ■ 4.0U4ESX ■ 4.0U4 ESX i ■ 4.1U2ESX ■ 4.1U2ESX i ■ 5.0 U1(ESXi) ■ 5.1/5.5, ESXi	Version 18.00.00.00.1VMW
FreeBSD® x64 and x32 ■ 7.2 and 7.4 ■ 8.2 and 8.3 ■ 9	Version 18.00.00.00
Oracle VM (OVM) Server x64 and x32 ■ 3.0	Version 18.00.01.00-1
NYTRO WARPDRIVE AND NYTRO XP6209 FIRMWARE/BIOS	**FIRMWARE PACKAGE VERSION**
Nytro WarpDrive and Nytro XP6209 firmware revision	112.00.06.00
Nytro WarpDrive and Nytro XP6209 package revision	12.00.06.05
Nytro WarpDrive and Nytro XP6209 BIOS revision	110.00.00.00
Nytro WarpDrive and Nytro XP6209 UEFI BIOS	7.18.05.03
NYTRO FLASH MODULE	**VERSION**
1E512	5.5.3
SEAGATE UTILITY	**VERSION**
DDCLI for Linux, Windows, VMware, FreeBSD, and Solaris	Version 112.00.06.00

Download the latest software components and drivers, from the Seagate website: http://www.seagate.com/about/contact-us/technical-support/.

Seagate Technology LLC
AMERICAS Seagate Technology LLC 10200 South De Anza Boulevard, Cupertino, California 95014, United States, 408-658-1000
ASIA/PACIFIC Seagate Singapore International Headquarters Pte. Ltd. 7000 Ang Mo Kio Avenue 5, Singapore 569877, 65-6485-3888
EUROPE, MIDDLE EAST AND AFRICA Seagate Technology SAS 16-18 rue du Dôme, 92100 Boulogne-Billancourt, France, 33 1-4186 10 00

Publication Number: DB07-000147-00
September 2014